Egan Marine Corporation, TDD #T05-9410-153

A. SPCC FIELD SHEET
(To be completed if SPCC Regulation is applicable to Facility - See 40 CFR 112.1)

1a. NAME OF FACILITY
Egan Marine Corporation/Service Welding and Shipbuilding

1B. TYPE OF FACILITY
Barge transporting of oils.

1c. FACILITY LOCATION

No Street Address is allotted by Cook County for the site. The facility is located northeast of Lemont, IL on the Sanitary Drainage and Ship Canal at mile marker 301.3. The facility sits on two peninsulas formed from rock quarries. N 41°41′06.4" W 87°59′15.9"

2a. NAME OF OWNER AND/OR OPERATOR RESPONSIBLE FOR FACILITY Dennis Egan, President/Owner

2b. TELEPHONE NUMBER (708) 739-0947

2c. MAILING ADDRESS

P.O. Box 669, Lemont, Illinois 60439

3. TYPES OF OIL STORED AND CAPACITY OF ABOVE GROUND AND BURIED STORAGE

The facility has a total of 43 tanks in use (approximately 945,500 gallons) with an additional 24 tanks (approximately 227,000 gallons) that were stated as not being in service, and a total of 800 to 1000 drums (approximately 50,000 gallons) of waste oil and vegetable oil. Some of the tank volumes within the following table were visually estimated by Danny Egan.

LOCATION	CONTENTS	ТҮРЕ	CAPACITY (gallons)	DIMENSIONS diameter x height (feet)
Western Peninsula	Vegetable based oils and animal grade soy bean oil.	Steel with glass lining, Cylindrical AST, Horizontally Oriented	7 X 25,000 gals	Unknown
II	u	Steel, Cylindrical AST, Horizontally Oriented	6 X 25,000 gals	П
и	n	Steel, Cylindrical AST, Vertically Oriented	22 X 27,000 gals	37' X 11'
П	Not in use.	Poly Tank	9 X 2,000 gals	Unknown
n	Diesel Fuel	Steel, Cylindrical AST, Horizontally Oriented	3 X 500 gals	11
n	Diesel/Asphalt/Oil Blend	11	1 X 8,000 gals	
П	II	Steel, Cylindrical AST, Vertically Oriented	2 X 8,000 gals	II
11	"	11	3 X 12,000 gals	tī
n .	II .		1 X 15,000 gals	Ti.
П	Homogenized vegetable oil sludge.	Steel 55 gallon Drum	600 to 700 X 55 gallon drums	н
Eastern Peninsula	Not in use.	Steel, Cylindrical AST, Horizontally Oriented	1 X 8,000 gals	11
II	и	Steel, Wrecked Tanker Trailers	3 X 10,000 gals	u
11	н	II .	1 X 5,000 gals	11
п	n	Steel, Cylindrical AST, Vertically Oriented	3 X 15,000 gals	и
11	П	u	2 X 20,000 gals	11
11	u .	Steel, Cylindrical AST, Horizontally Oriented	1 X 15,000 gals	t a
	11	u	2 X 8,000 gals	

A. SPCC FIELD SHEET (To be completed if SPCC Regulation is applicable to Facility - See 40 CFR 112.1)							
LOCATION	CONTENTS	TYPE	CAPACITY (gallons)		DIMENSIONS diameter x height (feet)		
Eastern Peninsula	Spilled oil from emergency response clean ups.	Steel 55 gallon Drum		300 to 400 X 55 unk			
	4. IS A CERTIFIED SPCC PLAN AVAILABLE FOR INSPECTION? [] YES [X] NO The facility did not have an SPCC plan prepared for the oil storage. 5. DATE OF INSPECTION October 20, 1994						
6. NAME AND REGIST	6. NAME AND REGISTRATION NUMBER OF CERTIFYING ENGINEER [X] NOT AVAILABLE 7. DATE SPCC PLAN WAS CERTIFIED [X] NOT AVAILABLE						
8. IS THE SPCC PLA	8. IS THE SPCC PLAN FULLY IMPLEMENTED? [] YES [] NO [X] NOT APPLICABLE						
9. NAME OF WATER BODY THAT POTENTIAL SPILL COULD ENTER: OR IF UNNAMED TRIBUTARY, THEN FIRST WATERBODY DOWNSTREAM The Sanitary Drainage and Ship Canal and the Des Plaines River.							
Woodland Park Comme Coast Guard, to dis 0945 hours and met presented with a fa facility was then i and Trebilcock depa returned to the fac	10. COMMENTS At 0900 hours on October 20, 1994, TATM Krieg arrived at the U.S. Coast Guard offices at 215 West 83rd Street in Woodland Park Commerce Center. The TAT, OSC Len Zintak and SPCC Coordinator Barbara Carr met with Mike Trebilcock, U.S. Coast Guard, to discuss Egan Marine Corporation. Krieg, Zintak, Carr and Trebilcock arrived at Egan Marine Corp. at 0945 hours and met with Dennis Egan, President of Egan Marine and his son Danny Egan, Vice-President. Dennis Egan was presented with a facility information packet by OSC Zintak, and was given a brief description of its contents. The facility was then inspected by Krieg, Zintak, and Carr under the escort of Dennis and Danny Egan. Krieg, Zintak, Carr and Trebilcock departed the facility at 1305 to obtain more film for photodocumentation. Krieg, Zintak and Carr returned to the facility at 1410 hours to complete the photos. The site inspection was completed at 1430 hours.						
The facility consists of numerous oil storage tanks of volumes greater than 10,000 gallons. The facility is located on two connected peninsulas of land. Storage tanks were located on both peninsulas. Egan Marine Corp. barges and tug boats were located in the water between the two peninsulas. Please refer to the facility diagram at the back of this report for further details on the location of storage tanks.							
11a. SPCC NO.	11b. CASE NO.	11c. NPDES NO.	[X] NOT	APPLICABLE			
12a. INSPECTOR (si	gn) Sunul Isr	in		12b. DA1	TE 19/24/94		

12c. INSPECTOR (print)
Daniel Krieg, Ecology and Environment, Inc., Chicago

B. SPCC INSPECTION SUMMARY SHEET					
SPCC NO.	CASE NO.		DATE OF I	NSPECTION per 20, 1994	
NAME OF INSPECTOR (signature) Lunul Mring DATE OF			DATE OF D	F DOCUMENTATION REPORT	
NAME OF INSPECTOR (print) Daniel Krieg, Ecology and Environment, Inc., Chicago N/A					
	1. FA	CILITY			
a. COMPANY	in the diagram and Chiphuilding				
	vice Welding and Shipbuilding				
ADDRESS P.O Box 669 (No address is	allotted to the site by Cook Co	ounty.)		TELEPHONE (708) 739-0947	
CITY Lemont		STATE IL		ZIP CODE 60439	
FACILITY NAME Egan Marine Corporation					
b. FACILITY LOCATION					
	theast of Lemont, IL on the San as formed from rock quarries.			: mile marker 301.3. The	
PARENT CORPORATION None					
ADDRESS					
CITY		STATE		ZIP CODE	
c. WATER BODY PROTECTE	D				
The Sanitary Drainage and SI	hip Canal and the Des Plaines R	iver.			
	2. Pi	JRPOSE			
INITIATION: [] ROUTINE SURVEILLANCE [X] COAST GUARD INFORMATION [X] SPILL REPORT [] CITIZEN COMPLAINT [] OTHER (specify)					
TYPE: [X] PLAN PREPARATIO	ON [X] PLAN IMPLEMENTATION [] PLAN AMENDMENT				
	3. INS	PECTION			
INDIVIDUAL CONTACTED Dennis Egan				TITLE President, Egan Marine	
INDIVIDUAL CONTACTED Danny Egan				TITLE Vice-President, Egan Marine	
NOTIFICATION Inspection Notification to Enotified the U.S. EPA of an or	Egan Marine was performed by OSO il release to the canal by Egan	Len Zintak on Octobe Marine prior to Octob	er 19, 1994 Der 19, 199	. The U.S. Coast Guard had	

B. SPCC INSPECT	ION SUMMARY SHEET			
4. FINDINGS	5. (None required if fac		CHMENTS is in appare	ent compliance)
SOURCE IN APPARENT COMPLIANCE WITH SPCC REQUIREMENTS:		NONE	ATTACHED	ALREADY ON FILE
[] YES [] HAVE ADEQUATE PLAN				
[] NOT SUBJECT TO REGULATIONS	*Detailed Observations	[]	[X]	[]
[] INSUFFICIENT STORAGE	*Photographs	[]	[X]	[]
[] NO REASONABLE SPILL EXPECTATION	Slides	[X]	[]	[]
[] PLAN FULLY IMPLEMENTED	Map	[]	[X]	[]
[] NEW FACILITY OPERATIONAL FOR LESS THAN 6 MONTHS	*Field Drawing	[]	[X]	[]
	*Comments	[]	[X]	[]
[X] NO	Telephone Conversations	[X]	[]	[]
[X] NO PLAN	*SPCC Plan	[X]	[]	[]
[] PLAN NOT PROPERLY CERTIFIED				
[] PLAN DOES NOT HAVE MANAGEMENT APPROVAL	*ALL REQUIRED IF FACILIT	Y IS N	OT IN APPARE	NT COMPLIANCE.
[] PLAN NOT MAINTAINED AT FACILITY MANNED 8 HOURS/DAY	If photos not permitted,	check	"NONE" and	explain. Add
[] INADEQUATE PLAN (detailed SPCC plan review attached)	"SPCC Plan to List of At	tachme	ents when app	propriate.
[] PLAN NOT FULLY IMPLEMENTED				•
[] PLAN NOT REVIEWED WITHIN 3 YEARS				
[] OTHER				

C. DETAILED SPCC DOCUMENTATION FACILITY Egan Marine Corporation/Service Welding and Shipbuilding DATE OF INSPECTION October 20, 1994

1. FACILITY DESCRIPTION

1a. TYPE OF BUSINESS/OPERATION

Barge transporting of oils.

1b. FACILITY OIL STORAGE

The facility has a total of 43 tanks in use (approximately 945,500 gallons) with an additional 24 tanks (approximately 227,000 gallons) that were stated as not being in service, and a total of 800 to 1000 drums (approximately 50,000 gallons) of waste oil and vegetable oil. Some of the tank volumes within the following table were visually estimated by Danny Egan.

LOCATION	CONTENTS	TYPE	CAPACITY (gallons)	DIMENSIONS diameter x height (feet)
Western Peninsula	Vegetable based oils and animal grade soy bean oil.	Steel with glass lining, Cylindrical AST, Horizontally Oriented	7 X 25,000 gals	Unknown
(1	u	Steel, Cylindrical AST, Horizontally Oriented	6 X 25,000 gals	н
n	u	Steel, Cylindrical AST, Vertically Oriented	22 X 27,000 gals	37' X 11'
п	Not in use.	Poly Tank	9 X 2,000 gals	Unknown
II	Diesel Fuel	Steel, Cylindrical AST, Horizontally Oriented	3 X 500 gals	
u	Diesel/Asphalt/Oil Blend	п	1 X 8,000 gals	II
11	u	Steel, Cylindrical AST, Vertically Oriented	2 X 8,000 gals	и
n	11	п	3 X 12,000 gals	II
n .		П	1 X 15,000 gals	н
н	Homogenized vegetable oil sludge.	Steel 55 gallon Drum	600 to 700 X 55 gallon drums	11
Eastern Peninsula	Not in use.	Steel, Cylindrical AST, Horizontally Oriented	1 X 8,000 gals	и
		Steel, Wrecked Tanker Trailers	3 X 10,000 gals	u
11	и	П	1 X 5,000 gals	11
#1	11	Steel, Cylindrical AST, Vertically Oriented	3 X 15,000 gals	н
п	11	п	2 X 20,000 gals	и
11	II	Steel, Cylindrical AST, Horizontally Oriented	1 X 15,000 gals	п
	. "	II.	2 X 8,000 gals	и
u	Spilled oil from emergency response clean ups.	Steel 55 gallon Drum	300 to 400 X 55 gallon drums	11

C. DETAILED SPCC DOCUMENTATION

1c. PREVENTION MEASURES PROVIDED

The facility did not have any adequate secondary containment measures for the oil storage tanks. The tanks were all in close proximity to the canal and Dennis Egan stated the facility is prone to flooding during periods of heavy rainfall. A shallow pit, approximately 100' X 75' X 1', which contained four 25,000 gallon tanks, was claimed by Dennis Egan to be the lowest area on the western peninsula. Egan stated that all of the runoff from the surrounding tanks flows to the pit. The shallow pit was not an adequate impermeable containment area because the base of the pit was made of fractured bedrock. An oil/water separator had recently been constructed to separate the liquid collected within the shallow pit area. Piping leading from the oil/water separator to the barge slip was cracked and leaking in two places. None of the tanks were indicated by Danny Egan to have visual or electronic volume gauges. Further, none of the tanks had failsafe engineering devices. Danny Egan did not know if the tanks had corrosion protection. Numerous tanks had fittings for steam heating. Dennis Egan did not indicate that the condensed water was inspected on a regular basis. Emergency spill response equipment in the form of booms and absorbents were shown to be readily available. The facility had adequate night lighting. parts of the perimeter had adequate fencing. None of the tanks had locks on the outlet valves.

Dennis Egan indicated that the tanks are inspected on a daily basis by the workers at the facility. No written protocol for tank inspection is used nor are records of the inspections kept. Dennis Egan indicated that if a leak is detected, the tank contents are emptied into another tank so that repairs may be performed. No records of tank repairs are kept. The truck loading and unloading areas are located on the west and east sides of the storage tanks. No signs are posted to warn truck drivers of damaging the tanks. The tanks are immediately adjacent to the loading/unloading areas and have no barrier to prevent damage to the tanks by trucks.

1d. APPEARANCE OF FACILITY (housekeeping)

The facility had numerous oil stains at various locations throughout the entire facility. The area surrounding the vegetable oil storage tanks on the western peninsula was saturated with oil. A fresh layer of white rock had recently been laid over the green and brown oil saturated soils. Water collected in a puddle near the homogenized vegetable oil waste drums contained an oily sheen and quarter size droplets of oil. Another water puddle to the west of the tanks also contained oil. The vegetable oil storage tanks and diesel/asphalt tanks showed signs of rust, flaking paint and oil staining. The eastern peninsula also had numerous multicolored stains on the ground and tanks. Puddles of oil and standing oil from spilled drums was found. The 55 gallon drums containing the oil waste from emergency response clean ups were found without lids or tipped over with the contents spilled on the ground. Some of the sealed drums stacked and covered with a tarp were found to have punctures that allowed the contents to drain out. Further, a pile of oil saturated soil was found alongside the mound of gravel debris on the eastern peninsula. One 15,000 gallon tank on the eastern peninsula had been punctured and insufficiently plugged. Danny Egan stated this tank was not in use, however, corresponding oil stains were found around the puncture in the tank and on the ground around the tank.

Dennis Egan did not divulge any information on past spill incidences that have taken place at the facility when he was questioned by TATM Krieg. Dennis Egan also indicated no written records were kept pertaining to spilled material.

2. RECEIVING WATER (should spill occur)

2a. NAME AND/OR DESCRIPTION

The Sanitary Drainage and Ship Canal to the south, and the Des Plaines River to the north.

- [X] Perennial [] Intermittent
- [X] Water present at time of inspection
- [] Inspector traced discharge to receiving water
- [] Inspector traced apparent drainage path to receiving water [] Receiving water identified by company representative
- [] Receiving water identified from topo map
- [X] Receiving water identified by other means (specify): U.S. Coast Guard

2b. PROBABLE FLOW PATH TO RECEIVING WATER

Any spill on the grounds of the facility would flow over land directly into the canal. Egan indicated that the grounds of the facility flood often in times of large rainfall. The Des Plaines River is adjacent to the facility to the north. A spill may enter the river through connecting water paths to the canal or during periods of flooding.

2c. HOURS FACILITY IS MANNED

The facility is in operation 24 hours a day.

C. DETAILED SPCC DOCUMENTATION

3. COMMENTS

The owner of the facility, Dennis Egan, was not aware of the regulations set forth in 40 CFR 112. The facility drainage consists of overland liquid flow into the Sanitary Drainage and Ship Canal. Egan Marine Corp. did not keep a listing of the tanks at the site. However, a partial listing of tanks was shown to be posted on boards in the workshop building adjacent to the oil storage tanks.

The means for oil transfer from the storage tanks to the barges was explained by Danny Egan to be done with 10,000 gallon tanker trucks. Tanker trucks are filled with oil on the west, north or south sides of the storage tanks. The trucks are then driven to the east side of the tanks along the barge slip where the oil is pumped into the barge.

The facility did not have a Certificate of Substantial Harm Criteria.

4. SPCC PLAN REVIEW

Not applicable. The facility did not have a spill prevention plan.

5. SPCC AMENDMENT RECOMMENDATIONS (amendment inspections only)

N/A





